

DATE 1702Z 18 MAR 64

TOP SECRET

TO : DIRECTOR
25X1A

FROM : [REDACTED]

ACTION:

INFO :

OPS 1-12

2	10
3	11
4	12
5	13
6	14
7	15
8	16

PRIORITY

TO 1826Z 18 MAR 64

25X1A

25X1A

IN 68633

25X1A

PRIORITY
25X1A

INFO PRIORITY

CITE 8451

103

A. 0024C

B. GOOD

C. THE 2L POSITION INDICATOR LAMP MALFUNCTIONED THRU-OUT THE 9R SIDE. WEAK IMAGES OF ADJACENT POSITION INDICATORS WERE IMAGED DURING EXPOSURE OF THE CORRECT POSITION INDICATORS THRU-OUT BOTH SIDES. CLOCK COUNTER FRAMES 134 THRU 267 ARE DEGRADED ON BOTH SIDES DUE TO EXCESSIVE AIRCRAFT MANEUVERING. THE LAST 6 FEET OF THE 9R SIDE AND THE LAST 3 FEET OF THE 9L SIDE WERE SEVERELY SCRATCHED AND ABRAIDED AS FILM EXHAUSTION BECAME IMMINENT. 9L FILM CONTAINS 10 FRAMES MORE THAN THE 9R.

END OF MESSAGE

TOP SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification